

PS/CO/MIN 88- 8

EXM-88-01

22. 3. 1988

10/03/88

PRESENTS__:

G. Daems , M. Leilezant , P. Heymans , J. Cuperus ,
P. Bobbio , P. Martucci , F. Perriollat , N.d.M-Noblat,

Part Time : P. Skarek , W. Heinze , G.P. Benincasa

Excusés : A.v.d. Scheuren , C.H. Sicard , L. Merard ,
F. Giudici , L. Casalegno , J. Philippe , C. Serre .

STATISTIQUE:

Linac/Lear

Interface Line Surveyor gave problems and was very
difficult to change it due to its situation .

A serial highway driver + Dataway display were changed

Complex PS

STARTUP:

The J version of SINTRAN III was installed in all the
FECs and a HENT was done as well . No real problems
were noticed except on EPA .

INIT of the EQ. Modules : The initialization tests
could not be done because the hardware was not
operational . This is unfortunate because a lot of
software tests could be done during shut-downs .

Restore of segment-data for PTIM and POW was done and
some problems arised with PTIM for the NOT USED
elements .

Problems with restore data for the GFAs of CPS and TT.
Backup files had to be used .

Problems , as well, with BFC , K71-79 , VSLP probably
for lack of good data for the INIT programs .

The list of EMs in the program DT-SSAVE has to revised.

In the future (how near ?) the data for INIT programs
will be included in the ORACLE data-base .

PSB :
action:
P.Martucci

POW-INIT has to be rewritten .
FREQ : The reload crate doesn't work properly .
INIT-FREQ was necessary to initialise the data-table
in the ACC .The same applies for FFG in CPS .

action:
J.M.Bouché
A.Gagnaire

The display of the beams current is not updated on the
console in BCER .

GFA: A capacitor burnt on the GFA matrix .
LOOP: The image in the ACC was changed with an old one
to take into account the fact that now we only have
Single Transciever of type 1.

CPS/TT :

RF-Diagnostic : does not seem to work. The displayed

date is old and is not updated . Gian Paolo thinks there are two possibilities :

- a) The hardware module clock is not working or not initialised ;
- b) Some RF timing pulses are not delivered by the RF people .

MDR-CPS : modifications of the program gave a lot of problems , in particular the use of MTIM .

BLM : The reload crate for both CPS ant TT did not work .

VLSP : error messages "cables not connected " and it was true!!!

L1C35 special camac module to alter the PLS telegram is not used anymore .

RFVA : has been modified . More news next week .

MTIM : software changed . Now only takes into account the channels being used

MTV now checks the "rest position" of the screens .

PLS archives : have been changed but the complete modification is dependent from the change of PLS for PS et PSB being done by J.Lewis

AA :

LPI:

POINTS DELIVRÉS:

The bit pattern for the memory test of the ACC has been changed to F000

DIVERS:

P.Martucci 11/03/1988

Distribution liste 4a

List 4a) **EXM DISTRIBUTION**

G.P. Benincasa, P. Bobbio, J. Boillot,
 J.M. Bouché, P. Burla, L. Casalegno, G. Cuisinier, J. Cupérus,
 G. Daems, A. Daneels, C. Dehavay, F. Di Maio,
 A. Gagnaire, F. Giudici, W. Heinze, P. Heymans, B. Kuiper,
 H. Larsen, M. Lelaizant, J. Lewis, E. Malandain, P. Martucci,
 L. Mérard, N. de Metz-Noblat, A. Pereira, F. Perriollat,
 J. Philippe, J.P. Potier, U. Raich, J. Redard, W. Remmer,
 Ch. Serre, G. Shering, C.H. Sicard, E. Sigaud,
 P. Skarek, A. van der Schueren, K. Zografos = 38