PRELIMINARY SET OF RULES FOR THE TTSM (CASE OF e+/e- OPERATIONS)

R. Garoby

Definitions

| Data | Data gathered by the TTSM |
|---------------------|--|
| Deduction | What can be logically deduced from data |
| Conclusion & Action | Clear expression of deduction and next action recommended for improving the diagnostics |
| Problem | Beam characteristics are probably not correct |
| Possible Problem | Suspicion that beam characteristics may be incorrect, but not certain |
| PS-RF | Equipment under the responsibility of the PS-RF team |
| SPS | Equipment under the responsibility of SPS teams |
| Timing | Equipment under the responsibility of the PS-CO team |
| KFA | Equipment under the responsibility of the PS-PA team |
| <u>continuously</u> | confirmed over more than 10 consecutive acquisitions with |
| | beam |
| other means | other acquisition systems (computer generated displays and/or analog signals observation) |
| beam present | URE95 gives a measurement |

Conclusions are of different kinds:

- "OK" conclusions state that a system or sub-system is working correctly. There is an implicit hierarchy between these statements: for example, if everything is declared OK, it is not necessary to investigate deeper. An "OK" statement requires that the required conditions are met <u>continuously</u>.
- "Not OK" conclusions are obtained whenever the required conditions are met. Some require that <u>beam is present</u>, others do not.
- Whenever possible the specific pieces of equipment which can be suspected are given.

Other remarks:

- the threshold for decision are indicative, and are likely to be modified with experience.
- the present rules are probably imperfect and will need to be corrected "on line". It is very important that the analyzing system clearly declares which rules he uses to arrive at a given recommendation (if any...).
- Part of the installation may not be operational. The analysis should still proceed with the remaining part, and tolerate the recurrent messages of warning.

Interpretation of data from TTSM-Ejection


| Rule | Data | Deduction | Conclusion & Action |
|------|--|--|---|
| nb. | | | |
| 1 | URE95 is <u>continuously</u> within 2 ns from reference | Beam is properly synchronized w.r.t. the trains used by the ejection timings. | Everything is OK |
| 2 | URE95 is within 2ns from reference +- k*261.4 ns (k is not 0) | Beam is probably properly synchronized but some bunches are missing | Beam Problem: missing bunches |
| 3 | URE95 is more than 3 ns from reference | Beam is not properly synchronized w.r.t. the trains used by the ejection timings, or some bunches are missing | Problem: - investigate using the other data |
| 4 | No measurement for URE95 | No beam at ejection, or beam intensity too small for a good measurement, or PU signal disconnected | Possible Beam Problem: - assume that "beam is not present" in the rules - investigate by other means |
| 5 | No refreshment of TTSM- Ejection data | Start ejection timing is not generated (PX.WDT), or control system in trouble | Possible Timing or Control Problem: - investigate by other means |
| 6 | The difference between ITRVSPS and URE95 is <u>continuously</u> within 2 ns from the difference between references | Beam is properly synchronized w.r.t. the reference trains | PS-RF is working OK: - if there is a problem it is likely to come from other equipment |
| 7 | The difference between ITRVSPS and URE95 is within 2 ns from the difference between references +- k*261.4 ns (k is not 0) | Beam is probably properly synchronized but some bunches are missing | Beam Problem: missing bunches |
| 8 | The difference between KFA 71-79 and URE95 is <u>continuously</u> within 30 ns (modulo 2091 ns) from the difference between references | Kicker position is OK for a proper ejection | Kicker timing is OK w.r.t. the beam |
| 9 | KFA71-79 is not within 30 ns of reference | Kicker position is different from reference | Possible Problem: Kicker timing is not OK: - check control values in ejection timings - check transmission of PX.WDT to TTSM |


| 10 | The difference between | TRV train tracks properly the | TRV train is OK |
|----|--|--|--|
| 10 | IITRVEJE and URE95 is | beam position until ejection | |
| | continuously within 2 ns from | | |
| | the difference between | | |
| | references +- k*261.4 ns | | |
| 11 | The difference between | TRV train is probably not OK | Possible PS-RF problem: |
| | I1TRVEJE and URE95 differs | | - analyze TRV train with |
| | by more than 6 ns from the | | TTSM-Injection |
| | difference between references | | |
| | +- k*261.4 ns | | |
| | and beam is present | | |
| 12 | ITRFEJE is continuously | Start of ejection timing is OK | Ejection timing is using |
| 10 | within 2 ns from reference | w.r.t. the TRF train | the TRF train OK |
| 13 | I1TRVEJE is <u>continuously</u> within 5 ns from reference | Start of ejection timing is OK | Ejection timing is using |
| 14 | The difference between | w.r.t. the TRV train Beam frequency is OK (10 ⁻⁵ | the TRV train OK |
| 14 | Interaction of the second seco | from reference) | Beam frequency is OK: - check B field to be |
| | <u>continuously</u> within 1 ns from | | certain of beam energy |
| | the difference between | | certain of beam energy |
| | references | | |
| 15 | The difference between | Beam Synchronisation does | Beam frequency is not |
| | I1TRVEJE and I2TRVEJE is | not work, | OK: |
| | more than 2 ns from the | or the SPS trains are not | - apply the following rules |
| | difference between references | correct | - check control parameters |
| | and beam is present | | of PS-RF system |
| 16 | The difference between | Synchronisation frequency is | SPS RF train is OK: |
| | I1TRFSPS and I2TRFSPS is | OK (2. 10 ⁻⁶ from reference) | - can be confirmed more |
| | continuously within 2 ns from | | accurately with other RF |
| | the difference between | | measurements |
| 17 | references The difference between | Synchronisation frequency is | |
| 1/ | 11TRFSPS and 12TRFSPS is | not correct (> 3. 10^{-6} from | SPS problem: RF train is not OK |
| | more than 3 ns from the | reference) | - no action in the PS |
| | difference between references | | before correction is done |
| 18 | Rules 15 and 16 apply, and PS- | Beam control is not | PS-RF problem: |
| | RF control parameters are OK | synchronizing the beam | - call specialist |
| 19 | No measurement of KFA71-79 | KFA hardware is not pulsing, | Possible KFA problem: |
| | | or signal is disconnected from | - check KFA operation |
| | | TTSM | with other devices |
| 20 | No measurement of I1TRFSPS | No signal available for | Possible SPS or PS-RF |
| | or I2TRFSPS or ITRVSPS | synchronisation, | problem: |
| | | or it is disconnected from | - check signals with other |
| | | TTSM | devices |
| 21 | No measurement of ITRFEJE | TRF or TRV train not | Possible PS-RF problem: |
| | or I1TRVEJE or I2TRVEJE | available, | - check signals with other |
| | | or disconnected from TTSM | devices |

Interpretation of data from TTSM-Injection

| Rule | Data | Deduction | Conclusion & Action |
|------|---|--|--|
| nb. | | | |
| 1 | URE95 is <u>continuously</u> within 2 ns from reference | Timing of beam transfer works correctly | Transfer timings are OK |
| 2 | URE95 is more than 3 ns from reference | Timing of beam transfer may not be OK | Possible Problem: - investigate using other data - check control parameters for beam transfer |
| 3 | No measurement for URE95 | No beam at injection, or beam intensity too small for a good measurement, or PU signal disconnected | Possible Beam Problem: - assume that "beam is not present" in the rules - investigate by other means |
| 4 | No refreshment of TTSM- Injection data | Start injection timing is not generated (PX.WEPAEJ), or control system in trouble | Possible Timing or Control Problem: - investigate by other means |
| 5 | No measurement of KFA94 (e+) or KFA72(e-) | KFA hardware is not pulsing, or signal is disconnected from TTSM | Possible KFA problem: - check KFA operation with other devices |
| 6 | KFA94(e+) or KFA72(e-) is not within 30 ns of reference | Kicker position is different from reference | Possible Problem: Kicker timing is not OK: - check control values in injection timings - check transmission of PX.WEPAEJ to TTSM |
| 7 | KFA94(e+) or KFA72(e-) is <u>continuously</u> within 30 ns of reference | Kicker position is OK for a proper injection | Kicker timing is OK |
| 8 | SSEPINJ is <u>continuously</u> within 150 ns of reference | SSEPINJ is correct w.r.t. WEPAEJ | SSEPINJ is OK |
| 9 | SSEPINJ is more than 150 ns from reference | SSEPINJ is not correct w.r.t. WEPAEJ | Possible Problem: SSEPINJ may not be OK: - check control value of SSEPINJ - check transmission of PX.WEPAEJ and PX.SSEPINJ to TTSM |
| 10 | No measurement of SSEPINJ | SSEPINJ is not pulsing, or is disconnected from TTSM | Possible Problem: SSEPINJ may not be OK: - check control value of SSEPINJ - check transmission of PX.SSEPINJ to TTSM |

| _ | | | |
|----------|---------------------------------------|------------------------------|--------------------------------|
| 11 | I1TRFINJ is <u>continuously</u> | Start of injection timing is | Injection timing is OK w.r.t |
| | within 2 ns from reference | OK w.r.t. the TRF train | TRF train |
| 12 | I1TRVINJ is continuously | Start of injection timing is | TRV train is OK w.r.t. |
| | within 5 ns from reference | OK w.r.t. the TRV train | Injection timing |
| 13 | The difference between | Bunch tracking by the TRV | TRV train is OK after |
| | I2TRVINJ and URE95 is | train works correctly | injection |
| | continuously within 3 ns | | |
| | from the difference between | | |
| | references | | |
| 14 | The difference between | Bunch tracking by the TRV | Beam problem: missing |
| | I2TRVINJ and URE95 is | train works correctly but | bunches |
| | continuously within 3 ns | bunches are missing | |
| | from the difference between | | |
| | references +- k*261.4 ns (k | | |
| | is not 0) | | |
| 15 | The difference between | Bunch tracking by the TRV | Possible Problem: TRV train |
| | I2TRVINJ and URE95 is | train may not be correct | may not be OK: |
| | more than 4 ns from the | | - check with TTSM-Ejection |
| | difference between | | |
| | references +- k*261.4 ns | | |
| 16 | The difference between | Bunch tracking by the TRV | Problem: TRV train is not |
| | I2TRVINJ and URE95 is | train is not correct | OK: |
| | more than 7 ns from the | | - check B field at injection |
| | difference between | | - adjust RF phase at injection |
| | references +- k*261.4 ns | | - call PS-RF specialist |
| 17 | No measurement of | TRF or TRV train not | Possible PS-RF problem: |
| | I1TRFINJ or I2TRFINJ or | available, | - check signals with other |
| | I1TRVINJ or I2TRVINJ | or disconnected from TTSM | devices |
| 18 | If rules 15 or 16 apply and | Probably bad injection | Problem: probably bad |
| | beam losses are observed at | parameters | injection parameters |
| | low energy | | - check B field at injection |
| | | | - adjust RF phase at injection |
| | · · · · · · · · · · · · · · · · · · · | | - call PS-RF specialist |





ALQUISTION FOR et

| | | | ł | | | | • |
|--------------------------|--|---------|------------|------------|------------|----------|-------------------|
| File View Options | | | | | | | Help |
| SPP_INI | | | | | 4438 | 10 Nov | 10 Nov 9 18:04:40 |
| START ANDE FEWERAEJ | EJ | | | | | | |
| Chennel Names | Acquictions | Jtterrs | References | Telerances | TDC Result | | Signal Status |
| PX. SSEPINJ | 1008110 | 49 | 1008061 | 500 Ok | ok | | 5 |
| PX.IITHEIMJ | 520 | 1 | 613 | 2 | OK | ę | 5 |
| PX.IZTRFINJ | 1008693 | -6 | 1008699 | 500 | OK | Š | ð |
| PX.IITRVIMJ | 3868 | 1 | 3867 | 10 | OK | <u>s</u> | ð |
| PX.IZTRVINJ | 1011977 | 2 | 1011975 | 10 | OK OK | ð | OK |
| PI.KTAJA | 1005126 | -7 | 1005128 | 50 | 0¥ | | ok |
| No meaning | 1005484 | 20 | 1005479 | 50 OK | ok Xo | | 5 |
| PR. URE95 | 1004090 | T | 1004089 | • | Ok | | QK |
| Undreeze Freeze One Shet | Shet Open Kreb | Kob | | | | | |
| | | | | | | | |
| | | | | | | | |
| | A DESCRIPTION OF A DESC | | | | | | |

TYPICAL TTSN - TNJECTION

ACQUISTTION FOR ET

| | | | ž | | | | • |
|----------------------|---------------------------|------------|------------|------------|-----------|------------|--------------------|
| File View Options | | | | | | | Halp |
| START MAN, PX WEPAEJ | 3 | | | | MAS | | 11 Nov 10 14:40:13 |
| Chennel Names | Acquiritions | Jitters | References | Telerances | TDC Rendt | QSM Status | Signal States |
| PX. SSEPINJ | 1008023 | 5 1 | 1008032 | 500 | ok | 1 | ok |
| PX. I TTRFINJ | 617 | 7 | 621 | 5 | | Early | ok |
| PX.I2TRFIMJ | 1008569 | 9 | 1008575 | 500 | OK | Fault | OK |
| PX.ITTRVINJ | 3970 | 2 | 3968 | 5 | | ð | <u>s</u> |
| PX.I2TRVINJ | 1012075 | Ĩ | 1012074 | 500 | 6 | ¥ | <u>e</u> |
| No meaning | 1006125 | -2 | 1006127 | 20 | 6 | | ş |
| PI.KEA72 | 1004514 | 121 | 1004519 | 20 | <u>S</u> | | ş |
| PR. URE9 5 | 1005383 | 2 | 1005381 | C | ok | | <u>ę</u> |
| Untresse Freeze One | Frveze One Shed Open Kneb | Ent | | | | | |
| | | 1 | | | | | |
| | | | | | | | |
| | | | | | | | |

TYIZCAL TISN _ EJELTION ALQUENTION FOR et

| | | | 3 | | | | •] |
|-----------------------------------|---------------------------|---------|------------|------------|------------|------------|-----------------------|
| Pile View Options | | | | | | | Help |
| LA ALS | | | | | | P 11 Nov | SPP 11 Nov 9 18:42:08 |
| START ander PX WPS16 | | | | | | | |
| PS REV Programs: 677.119995 KHz | 119995 KHz | | | | | | |
| SPS RF Prepring: 200.294913 Miliz | 94913 MTE | | | | | | |
| Channel Names | Acquisitions | Jitters | References | Telerances | TDC Result | QSM States | Signal States |
| PX.ITREJE | 755 | 0 | 155 | 2 | ok | | ok |
| PX.ITRVEJE | 2750 | • | 2750 | 50 | ok | Fault | ok |
| PX.I2TRVEJE | 103350 | • | 103350 | | 0¥ | Fault | Š |
| PX.IITRESPS | 12725 | -6062 | 18787 | 23000 | OK | Fault | OK |
| PX.I2TRF8P8 | 1165441 | -6062 | 1171503 | 23000 | | Fault | ę |
| PX.ITRV8P8 | 20961 | 0 | 20961 | 50 | ð | | <u>e</u> |
| PR. KFA71-79 | 156713 | 9 | 156719 | 50 | ok K | | OK K |
| PR. URE9 5 | 28 | • | 58 | | Ok | | QK |
| Undrease Freeze On | Freeze One Shot Open Knab | d and a | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Typical TISN _ EJECTION ACQUISTITION FOR E

| | | | ÿ | | | | |
|----------------------------------|---------------------------|---------|------------|------------|--|------------|-----------------------|
| File View Options | | | | | | | Help |
| IA'NAS | | | | | 48 | (11 NOV | SPN 11 Nov 9 18:43:06 |
| START thete: PX WPSS | 2 | | | | | | |
| PS REV Frequency: 477.119995 KHz | 119995 KHz | | | | | | |
| SPS RF Prepring: 202,04913 MHz | 19913 Mite | | | | | | |
| Chevel Nerves | Acquisitions | Jitters | References | Telerances | TDC Readt | QSM Status | Signal Status |
| PX.ITREE | 558 | 0 | 558 | 5 | 5 Ok | | OK |
| PX.IITRVEJE | 4123 | -1 | 4124 | 50 | 0k | Fault | 0k |
| PX.I2TRVEJE | 104724 | -1 | 104725 | 20 | OK | Fault | <u>S</u> |
| PX.IITP22P8 | 20865 | 14406 | 6459 | | <u>o</u> k | Fault | <u>ok</u> |
| PX.I2TRESPS | 1173501 | 14406 | 1159175 | | | Early | OK |
| PX.ITRVSP8 | 20240 | - | 20239 | | ð, | | ð |
| PR. KPA71-79 | 156626 | 11 | 156615 | 50 | | | 0k |
| P.R. URES 5 | 269 | | 270 | | 0k | | Š |
| Untreced Freed On | Frezel One Shot Open Kueb | 3 | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | A REAL PROPERTY OF A REAL PROPER | | |