


Madame Patricia MARTUCCI E-6

CERN LIBRARIES, GENEVA

ISR PERFORMANCE REPORT

CM-P00072467

Physics Run Analysis No. 4 - 1979.Period 6 - Run 1074 to run 1088  
(14 November to 19 December 1979)1. Introduction:

The physics running requirements for this last period of 1979 were at 31.1 GeV/c (8runs) and 22.5 GeV/c (3 runs).

Throughout this period many runs were perturbed by accidental beam losses due to 18 KV power failures (runs 1077-1087-1088), power supply faults (1081-1083-1084) and water cooling problems on the SFM and the R1 main magnet (runs 1077-1085).

During run 1085, when the ISR was powered with one single transformer, the switch-on of R1 main magnets was the cause of a power surge and the consequent 18KV dip switched off probably some auxiliary power supplies of ring 2.

Beam 2 was lost and pierced a hole in the vacuum chamber in SS416.

About 50 hours were lost for physics due to repair.

Experiments R 209 and R 607 achieved to take data during this period.

A complete summary of 1979 physics runs is given at the end of this report.

The total stable beam hours has reached 2360 hours of which 91 hours were needed for beam adjustments, clean-ups, Q shifts etc.

The total integrated luminosity over the whole year and calculated with I5 reference monitors has reached  $1,28 \cdot 10^{38} \text{ cm}^{-2}$ .

2. Filling conditions:

Table I shows the main filling parameters and the performance achieved at the start of data taking for each run.

Four runs were filled at 22 GeV/c without any major difficulties (with one refill during run 1077). Including three refills (runs 1081-1084-1085), eleven runs were at 31.4 GeV/c. The last part of run 1088 (31.4 GeV/c) was also perturbed and refilled at 26.6 GeV/c in order to complete the experiment in I6 which was scheduled to stop at the end of the year.

The acceleration procedure went in general very smoothly. Some difficulties were however experienced during runs 1081, when both 31.4 GeV/c beams were lost during the final beam optimisation. Beam 2 was lost again later during the acceleration process.

In order to reduce the losses due to beam-beam effects, six mm vertical beam separation were usually applied in each intersection before stacking and

accelerating the second beam. Careful attention was paid to the working lines, the closed orbits and also the stack stability by means of the FFT during the acceleration procedure.

Due to saturation problems, co measurements with RF acceleration sweeps appeared to be unreliable. Therefore computer calculated corrections for orbit distortion were not applied in some cases and do explain part of our difficulties.

By using the BLC'S and optimising the cavity voltages, the losses per RF sweep could be maintained at a low value (5-15 mA). A few random RF sweeps with high current losses (50-100 mA) were observed during runs 1084-1085-1087-1088, and may explain some of the beam losses during acceleration.

### 3. Physics running conditions and behaviour:

The following table gives the total stable beam time and the integrated luminosity achieved during this running period.

Momentum GeV/c	Stable beam hours	$\int_x$ Luminosity time $10^{35} \text{ cm}^{-2}$
22	172	100,4
26	15	7,7
31	250	169,7

During this last period, the periodic background structure in ring 2 was again present during many 31.4 GeV/c runs (1074-1079-1083-1084-1085) perturbing strongly I1 and I4. The background structure has not been observed during 22 GeV/c runs.

During run 1084 an interesting observation was made through the FFT device: a strong horizontal transverse excitation peak was detected, in beam 2. Some correlations could be made with the background periodicity but further investigations will be necessary in order to understand better the cause of this strange frequency excitation. On the other hand, no correlation with the background structure could be observed by varying some magnets water cooling temperature inlet.

I1 and I4 who were generally perturbed by the background periodicity, recovered generally good workable conditions when doing clean-ups and/or vertical beam steerings. Collimation helped also in reducing the general high background levels.

Spikes on beam 2 background could be correlated with small power supply current changes in Low-B quadrupoles (1079), LBQ8 and LBQ9 hardware faults were also

the cause of 3 beam losses 1081/R1 - 1083/R2 - 1084/R1.

Coupling compensations in the presence of a stack using the FFT device were applied during a few runs (1075-1084-1088) and gave promising results i.e. improving the current decay rates and the luminosity decrease (See: PR.17.8.79, Observation of coupling using the BTF and PR 17.1.1980, Observations and Measurement of Betatron Coupling on Physics stacks by J.P. Koutchouk).

After the repair of the hole in the vacuum chamber in sector SS416 the ISR has been powered through the 3 CERN transformers (runs 1087 - 1088). The introduced PS booster cycle were clearly seen on the background recorders.

#### 4. Conclusions:

A lot of time was lost for physics due to unusual 18 KV perturbations, high level of hardware fault and a hole pierced in beam 2 vacuum chamber. Acceleration to 31.4 GeV/c is still time consuming and needs good optimisation of all machine parameters.

Based on beam transfer function observations, the operational use of the FFT device turned out to be a necessary and convenient tool for optimising beam diagnostics and the study of beam instabilities.

F. Lemeilleur

T. Verbeeck

FILLING PARAMETERS  
 \*\*\*\*\*

RUN	P1 P2 GLV/C		WL1	WL2	SHAVING %		DENSITY A/III		STACK				I. INITIAL AMP.		REF F III		DE/DT %/I. I/II.	L. JNIT 10E30
	R1	R2			R1	R2	R1	R2	R1	TOP R2	R1	BOTTOM R2	R1	R2	III	III		
1075	22	22	SB	SB	30	30	.45	.48	35	36	-35	-30	31.04	31.77	4.9	7.5	2.2	20.0
1077	22	22	SB	SB	30	30	.53	.55	35	33	-28	-28	35.93	34.08	4.4	6.5	1.3	28.0
1077	22	22	SB	SB	30	30	.53	.53	35	33	-33	-32	33.50	33.73	4.8	5.3	1.2	23.4
1078	22	22	SB	SB	30	30	.55	.49	34	34	-31	-32	35.44	32.29	5.1	8.0	1.8	22.6
1088	26	26	AC	AC	25	25	.55	.54	34	36	-14	-11	26.12	25.57	4.1	5.3	1.9	16.0
1074	31	31	AC	AC	25	25	.50	.46	32	30	-36	-37	34.01	30.73	4.4	5.8	.7	23.4
1079	31	31	AC	AC	25	25	.50	.46	35	34	-37	-36	34.72	33.26	4.1	5.5	.8	28.4
1081	31	31	AC	AC	30	30	.44	.49	34	33	-29	-34	27.28	32.25	4.1	4.2	.6	21.4
1081	31	31	AC	AC	30	30	.53	.46	30	34	-31	-32	31.59	31.93	4.1	4.9	1.0	24.8
1083	31	31	AC	AC	30	30	.54	.46	32	33	-35	-34	36.06	35.58	4.3	4.5	.7	25.8
1084	31	31	AC	AC	30	30	.52	.48	33	30	-37	-35	35.92	31.16	4.9	6.0	.5	22.8
1084	31	31	AC	AC	30	30	.46	.48	35	33	-28	-31	28.68	30.70	4.5	4.6	.3	19.4
1085	31	31	AC	AC	30	30	.54	.51	31	29	-36	-37	34.01	34.01	4.8	5.2	1.6	24.5
1087	31	31	AC	AC	30	30	.42	.34	26	34	-32	-33	23.45	22.49	4.8	5.5	.5	11.1
1088	31	31	AC	AC	30	30	.42	.46	39	32	-31	-36	28.99	30.69	4.6	5.5	.7	18.6

Table 1



FILLING PARAMETERS  
\*\*\*\*\*

RUN	P1 P2		AL1	AL2	SHAVING		DENSITY		STACK				I. INITIAL		HEFF		DH/DT	L. UNIT
	GV/C				R1	R2	R1	R2	TOP	BOTTOM	R1	R2	TI	FTI	TI	FTI		
1041	15/15		LR	LR	25	25	.35	.35	33	33	-26	-26	20.55	10.50	4.0	8.2	1.7	6.3
1042	15/15		LR	LR	30	30	.39	.39	26	28	-32	-31	23.65	10.64	6.0	7.5	.8	7.5
1043	15/15		LR	LR	30	30	.39	.39	32	32	-24	-22	16.92	10.10	3.0	7.3	.7	5.4
1044	15/15		LR	LR	25	25	.33	.35	36	33	-11	-10	17.84	10.07	3.0	6.7	.5	4.8
1045	22/22		SR	SR	25	25	.50	.52	31	29	-30	-29	19.92	10.07	4.0	5.9	1.1	5.9
1046	22/22		SR	SR	25	25	.48	.52	35	30	-23	-22	20.92	10.04	4.0	5.5	1.1	5.5
1047	22/22		SR	SR	25	25	.46	.50	37	41	-17	-17	19.92	10.03	4.0	5.5	1.1	5.5
1048	22/22		SR	SR	25	25	.52	.53	33	33	-26	-26	30.82	10.05	4.0	6.7	1.1	6.0
1049	22/22		SR	SR	25	25	.48	.53	37	33	-26	-26	30.82	10.43	4.0	7.4	1.1	6.7
1050	22/22		SR	SR	25	25	.47	.50	40	40	-26	-26	30.82	10.05	4.0	7.0	1.1	6.0
1051	22/22		SR	SR	25	25	.46	.51	33	40	-32	-33	29.49	10.80	4.0	7.1	1.1	6.0
1052	22/22		SR	SR	25	25	.44	.51	40	40	-22	-21	31.00	10.22	4.0	6.6	1.1	6.0
1053	22/22		SR	SR	25	25	.44	.53	40	39	-24	-24	27.99	10.05	4.0	6.6	1.1	6.0
1054	22/22		SR	SR	25	25	.48	.53	37	37	-25	-25	29.99	10.10	4.0	6.0	1.1	5.5
1055	22/22		SR	SR	30	30	.40	.51	33	38	-12	-22	16.45	10.75	4.0	5.4	2.2	7.7
1056	22/22		SR	SR	25	25	.35	.51	36	40	-20	-24	19.56	10.24	4.0	6.4	1.1	6.4
1057	22/22		SR	SR	30	30	.42	.50	38	38	-11	-24	20.51	10.17	4.0	6.4	1.1	6.4
1058	22/22		SR	SR	30	30	.53	.54	33	31	-26	-26	31.20	10.86	5.5	7.1	1.1	6.9
1059	22/22		SR	SR	30	30	.49	.54	33	33	-11	-30	30.77	10.04	5.5	5.5	1.1	6.0
1060	22/22		SR	SR	30	30	.47	.54	35	33	-11	-31	29.46	10.76	5.5	7.3	1.1	6.2
1061	22/22		SR	SR	30	30	.52	.55	33	33	-26	-31	31.68	10.21	4.0	6.2	1.1	6.4
1062	22/22		SR	SR	25	25	.62	.55	35	33	-28	-31	35.65	10.65	5.5	6.7	1.1	6.4
1063	22/22		SR	SR	30	30	.44	.55	34	34	-35	-30	30.12	10.12	4.0	7.7	1.1	6.9
1064	22/22		SR	SR	30	30	.44	.55	34	34	-29	-30	31.69	10.69	4.0	6.6	1.1	6.6
1065	22/22		SR	SR	30	30	.53	.53	30	33	-31	-28	32.35	10.35	4.0	7.7	1.1	6.5
1066	22/22		SR	SR	30	30	.60	.55	33	33	-30	-30	33.65	10.65	4.0	8.8	1.1	6.9
1067	22/22		SR	SR	30	30	.44	.55	33	34	-34	-30	29.49	10.35	4.0	7.7	1.1	6.5
1068	22/22		SR	SR	30	30	.49	.55	33	33	-30	-30	30.92	10.92	4.0	7.9	1.1	6.9
1069	22/22		SR	SR	30	30	.58	.55	30	33	-32	-27	35.52	10.52	5.5	6.5	1.1	6.5
1070	22/22		SR	SR	30	30	.62	.56	34	34	-30	-30	36.60	10.60	5.5	6.8	1.1	6.7
1071	22/22		SR	SR	30	30	.55	.54	34	34	-30	-30	32.33	10.33	4.0	6.6	1.1	6.6
1072	22/22		SR	SR	30	30	.40	.54	37	33	-31	-30	27.42	10.42	4.0	6.6	1.1	6.6
1073	22/22		SR	SR	30	30	.54	.55	34	30	-28	-30	33.21	10.21	4.0	6.6	2.2	6.6
1074	22/22		SR	SR	30	30	.45	.55	35	36	-35	-30	31.77	10.77	4.0	7.5	2.2	6.9
1075	22/22		SR	SR	30	30	.58	.55	33	33	-28	-28	35.08	10.08	4.0	6.6	1.1	6.6
1076	22/22		SR	SR	30	30	.56	.53	35	33	-33	-32	33.73	10.73	4.0	6.6	1.1	6.6
1077	22/22		SR	SR	30	30	.55	.40	34	34	-31	-32	35.29	10.29	4.0	6.6	1.1	6.6
1078	22/22		SR	SR	30	30	.55	.40	34	34	-31	-32	35.29	10.29	4.0	6.6	1.1	6.6
1079	22/22		SR	SR	30	30	.55	.40	34	34	-31	-32	35.29	10.29	4.0	6.6	1.1	6.6
1080	22/22		SR	SR	30	30	.55	.40	34	34	-31	-32	35.29	10.29	4.0	6.6	1.1	6.6
1081	31/31		AC	AC	25	25	.43	.44	32	32	-31	-31	27.50	10.50	4.0	6.6	1.1	6.6
1082	31/31		AC	AC	25	25	.39	.38	31	25	-32	-41	25.98	10.42	5.5	6.0	.8	5.5
1083	31/31		AC	AC	40	40	.39	.37	35	34	-28	-27	23.98	10.39	4.0	5.6	.8	5.6
1084	31/31		AC	AC	30	30	.29	.45	33	35	-37	-32	19.37	10.50	4.0	6.1	.7	5.7
1085	31/31		AC	AC	30	30	.43	.43	34	37	-32	-27	28.49	10.34	4.0	6.0	.7	5.7
1086	31/31		AC	AC	30	30	.41	.43	34	36	-32	-32	28.26	10.26	4.0	6.0	.7	5.7
1087	31/31		AC	AC	25	25	.42	.40	27	34	-27	-34	22.93	10.39	4.0	5.5	1.1	6.0
1088	31/31		AC	AC	30	30	.45	.47	35	32	-32	-36	28.99	10.59	4.0	5.4	1.1	6.0
1089	31/31		AC	AC	30	30	.48	.47	34	33	-36	-36	28.99	10.70	4.0	5.4	1.1	6.0
1090	31/31		AC	AC	30	30	.45	.45	34	34	-32	-35	26.53	10.04	4.0	6.0	1.1	6.0
1091	31/31		AC	AC	30	30	.45	.39	35	34	-36	-34	31.84	10.96	4.0	6.0	.7	6.0
1092	31/31		AC	AC	25	25	.38	.47	36	35	-38	-35	27.97	10.72	4.0	6.6	.6	6.6
1093	31/31		AC	AC	25	25	.35	.47	26	35	-38	-34	27.97	10.40	4.0	6.6	.7	6.6
1094	31/31		AC	AC	15	15	.36	.45	35	37	-37	-34	25.56	10.21	6.0	6.7	.9	6.7
1095	31/31		AC	AC	20	20	.46	.49	34	34	-34	-35	30.48	10.48	4.0	6.6	.9	6.6
1096	31/31		AC	AC	20	20	.46	.49	34	33	-37	-34	32.80	10.80	4.0	7.2	.7	7.2
1097	31/31		AC	AC	20	20	.42	.44	33	30	-37	-34	28.46	10.46	4.0	6.6	.7	6.6
1098	31/31		AC	AC	20	20	.44	.47	32	35	-36	-32	30.24	10.53	4.0	6.6	.7	6.6
1099	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1100	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1101	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1102	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1103	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1104	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1105	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1106	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1107	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1108	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1109	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1110	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1111	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1112	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1113	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1114	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1115	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1116	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1117	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1118	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1119	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6
1120	31/31		AC	AC	20	20	.40	.44	33	33	-37	-36	28.46	10.46	4.0	6.6	.7	6.6

SPECIAL COMMENTS  
\*\*\*\*\*

1041	LR+SOL, FAIRLY GOOD COND, CLEAN-UPS FOR I4, SOME SPIKES IN R1.	15 GeV/c
1042	LR+SOL+AFM, QUITE GOOD WORKING CONDITIONS.	
1043	LR+SOL+AFM, GOOD RUNNING COND, BEAMS LOST DUE TO SOL FAULT, REFILL.	
1044	LR+AFM, VERY GOOD CONDITIONS, LOW BACKGROUNDS.	
1045	LR+SOL+AFM, VERY STABLE BEAMS LOST DUE TO VACUUM VALVES CLOSURE, REFILL.	
1046	FAIRLY GOOD COND, SPIKES, BEAMS BLOWN-UP AT THE END.	
1047	LR+SOL+AFM, QUITE GOOD WITH SOME SPIKES, BG STRUCTURE IN R1.	
1048	GOOD COND AFTER CLEAN-UPS, BG INCREASING RAPIDLY, BEAMS LOST DUE TO VACUUM.	
1049	LR+SOL+AFM, QUITE GOOD COND, CLEAN-UPS IN R1 FOR I1+I2.	
1050	LR+SOL+AFM, VERY GOOD COND, BEAMS LOST DUE TO DAEM INTERLOCK FAULT, REFILL.	
1050	GOOD COND EXCEPT FOR I1 R1, SPIKY AT THE END, BEAMS BLOWN-UP, REFILL.	22 GeV/c
1050	LR+SOL+AFM, QUITE GOOD COND, LOW BACKGROUNDS.	
1052	LR+SOL, STABLE AND GOOD COND, BEAMS LOST DUE TO SOLENOID FAULT, REFILL.	
1054	LR+SOL+AFM, VERY QUIET BG, R1 LOST DUE TO PRESSURE RISE IN S51, REFILL.	
1054	GOOD COND, HIGH LOSS RATE IN R1 DUE TO PRESSURE BUMP, R2 LOST AT THE END.	
1055	GOOD COND, BG STRUCTURE IN R1, LIMITED CURRENT IN R1 DUE TO PRESSURE BUMP.	
1056	GOOD AND QUIET COND WITH FEW CLEAN-UPS, AT THE END BEAM 2 ONLY FOR I1.	
1058	LR+SOL+AFM, QUIET COND, SMALL CURRENT LOSSES IN R2.	
1059	LR+SOL+AFM, SPIKES PERTURBED COND, IN I4, R1 LOST DUE TO UNKNOWN FAULT.	
1059	REFILL, LR+SOL+AFM, FAST BLOW-UP I1 R1, SOME SPIKES IN R1+P2.	
1059	BOTH BEAMS LOST DUE TO 18KV.	
1061	LR+SOL+AFM, STABLE AND QUIET COND, R1 LOST DUE TO UNKNOWN FAULT.	26 GeV/c
1061	REFILL, R1, LR+SOL+AFM, CLEAN-UP FOR I2, SOME SPIKES IN BOTH BEAMS.	
1062	LR+SOL+AFM, GOOD COND, DETERIORATING FOR I2, CLEAN-UPS MAINLY FOR I2.	
1062	SMALL CURRENT LOSSES IN R1.	
1064	SOL+LR+AFM, GOOD COND, CLEAN-UPS FOR I2, SPIKES WITH HIGH BEAM LOSSES IN R1+R2.	
1065	LR+SOL+AFM, VERY GOOD AND STABLE WORKING COND, CLEAN-UPS FOR I4.	
1067	SOL+LR+AFM, GOOD COND WITH GRUNNING-UP BACKGROUND FOR I2, SPIKES IN R1.	
1067	REFILL, LR+SOL+AFM, GOOD COND, CLEAN-UPS FOR I2, COLL VERY EFFECT IN BG REDUCT.	
1068	SOL+LR+AFM, GOOD COND, LARGE SPIKES IN R2, R1 LOST DUE TO 18KV SPIKES.	
1069	SOL+LR+AFM, BACK STRUCTURE IN R2, SMALL AND LARGE CURRENT LOSSES IN R2.	
1069	BEAM 2 LOST DUE TO POWER SUPPLY FLUCTUATION.	
1070	SOL+LR+AFM, GOOD TO FAIR COND, IN I4, BOTH BEAMS LOST DURING Q-SHIFT IN R1.	
1070	REFILL, SOL+LR+AFM, GOOD COND, SMALL SPIKES IN R1+P2, CLEAN-UPS MAINLY FOR I2.	
1071	LR+SOL+AFM, PRETTY GOOD CONDITIONS.	
1071	LR+SOL+AFM, LOW BG GOOD COND, SMALL SPIKES IN R2.	
1075	LR+SOL+AFM, RATHER GOOD, CLEAN-UPS FOR I4+I5 IN R2.	
1077	LR+SOL+AFM, GOOD COND, HITSY IN R1, BEAMS LOST DUE TO POWER FAILURE, REFILL.	
1077	LR+AFM, SPIKES IN R1, BEAMS LOST DUE TO SEM WATER COOLING FAULT.	
1078	LR+AFM, GOOD TO FAIR COND, CLEAN-UPS + V STEERING FOR I1+I2+I8.	
1078	SOL+LR, FAIRLY GOOD COND, BEAM 2 LOST DUE TO P5 FAULT.	31 GeV/c
1078	REFILL, R2, GOOD AND STABLE WORKING CONDITIONS.	
1082	LR, SPECIAL RUN FOR 18 GOOD COND.	
1011	SFM+LB, QUITE GOOD CONDITIONS, MANY CLEAN-UPS.	
1013	SFM+LB, GOOD AND STABLE WORKING CONDITIONS, PRESENCE OF STRUCTURE ON R2 BG.	
1014	SFM+LB, QUITE GOOD COND, EXCEPT FOR I4 DISTURBED BY THE STRUCTURE ON R2 BG.	
1016	SFM+LB, RATHER GOOD CONDITIONS, VERY GOOD IN I8.	
1018	SFM+LB, GOOD WORKING CONDITIONS, MANY CLEAN-UPS TO IMPROVE I2 CONDITIONS.	
1019	SFM+LB, GOOD WORKING CONDITIONS, VERY FEW CLEAN-UPS.	
1020	SFM+LB+DAEM, QUITE GOOD RUN.	
1022	SFM+LR+DAEM, QUITE GOOD CONDITIONS, I3 PERTURBED BY R2 BG STRUCTURE.	
1023	SFM+LB+DAEM, QUITE GOOD WORKING CONDITIONS, VERY GOOD IN I8.	
1025	DAEM+LR, GOOD TO FAIR I1+I4 IN R2, LARGE AND REGULAR SPIKES IN R2.	
1026	COND AFTER CLEAN-UP.	
1026	DAEM+LR, SPIKES FROM TIME TO TIME IN R1+R2, DISTURBING I2+I4, P2 STRUCTURE.	
1028	DAEM+LB, GOOD COND AFTER CLEAN-UPS, BOTH BEAMS LOST DUE TO 18KV (THUNDERSTORM).	
1029	DAEM+LB, HIGH BG IN R2 FOR I2, VERY STABLE CONDITIONS.	
1030	SFM+LB+DAEM, GOOD AND STABLE WORKING CONDITIONS.	
1033	SFM+LB, VERY GOOD COND FOR ALL INTERSECTIONS, (SP) POWER FROM SINGLE TRANSFO.	
1034	SFM+LB ON, GOOD AND STABLE WORKING CONDITIONS.	
1036	LR ON, GOOD COND, BOTH BEAMS LOST DUE TO SFM FAULT, REFILL.	
1036	LR, REFILL, GOOD TO FAIR COND FOR I1+I2, MANY 18KV SPIKES, R1+R2 LOST, SFM FAULT.	
1037	SOL+LR ON, QUITE GOOD AND STABLE CONDITIONS.	
1038	SOL+LR ON, GOOD COND, R1 HAD TO BE DUMPED FOR SFM COMPENSATOR REPAIR.	
1038	SOL+LR, REFILL, R1, FAIR TO GOOD COND IN I1+I4, MANY CLEAN-UPS + BEAM ADJUSTEMENTS.	
1074	LR+SOL+AFM, BG STRUCTURE IN R2 PERTURBED I4, FAIRLY GOOD COND.	
1079	LR+SOL+AFM, QUIET AND STABLE BG, SOME SPIKES IN R2, BG STRUCTURE IN R2.	
1081	LR+SOL+AFM, R1 LOST DUE TO P5 FAULT, R2 LOST DURING Q-SHIFT, REFILL.	
1081	LR+SOL+AFM, FAIR COND IN R2, BAD FOR I4, SPIKES IN R2.	
1083	LR+SOL+AFM, IMPORTANT BG STRUCTURE IN R2, R2 LOST DUE TO P5 FAULT.	
1084	LR+SOL+AFM, GOOD COND, BG STRUCTURE, BEAMS LOST DUE TO SFM FAULT, REFILL.	
1084	LR+SOL+AFM, GOOD CONDITIONS.	
1085	LR+SOL+AFM, HIGH BG IN R2, STRUCTURE PERTURBED I1+I4, R1 LOST, R2 LOST 18KV REFILL.	
1085	R1 LOST WATER FLOW FAULT, R2 LOST WHEN POWERING MAIN MAG R1, HOLE IN VAC CHAMB.	
1087	LR+AFM, FAIR TO GOOD COND, I1+I4 HIGH BG.	
1088	LR+AFM, STABLE COND, BG SLOWLY INCREASING, BEAMS LOST DUE TO POWER FAILURE.	