

Table of contents

Preface	IX
Dedication to Mr Chow Chowkwanyun	X
<i>1. Ancient structures and historical monuments</i>	
Geotechnical causes of ancient tomb damage – Valley of the Kings, Egypt <i>J.B.Rutherford</i>	3
The consolidation of the Leaning Tower of Pisa and the preservation of the Venice Lagoon <i>F.Lizzi</i>	17
Geotechnical aspects of the salvage of the Egyptian monuments <i>A.H.El Ramle & M.M.Abdel Rahman</i>	35
Diagnostic analysis of the static conditions of some Italian monuments <i>P.P.Rossi</i>	41
Geotechnical engineering for the preservation of monuments and historical sites: The Italian case <i>C.Airo' Farulla, E.Battisti & R.Jappelli</i>	55
Geotechnical aspects of structures at the ancient city of Kausambi, India <i>R.K.Srivastava, A.V.Jalota, S.K.Duggal, G.K.Rai & B.B.Mishra</i>	67
Preservation of historical monuments at Mohenjodaro, Pakistan <i>I.Haq</i>	75
Geotechnical aspects of the restoration of historical monuments and the rehabilitation of infra-structures in Thailand <i>S.Promboon, S.Rasmibhuti, S.Kitjalaksana, D.T.Bergado, Prinya Nutalaya & A.S.Balasubramaniam</i>	81
Preservation and restoration of historic buildings: Two case histories <i>F.G.Bell</i>	129
<i>2. Recent structures – Buildings and water tower</i>	
Geotechnical aspects of the remedial works to the Supreme Court Building, Hong Kong <i>S.Butling</i>	143

Settlement and tilt of a large water tower <i>C.Di Maio & C.Viggiani</i>	155
Durability for the man-made constructions <i>F.Lizzi</i>	163
Restoration of the foundations of the old riverside storehouses in Porvoo, Finland <i>H.Koponen</i>	175
Underpinning experience in Singapore and Malaysia <i>B.E.Nord & G.G.Cheong</i>	181
Restoration of buildings and monuments in Vietnam <i>N.T.Tien, P.D.Long & B.Berggren</i>	187
3. Risk assessment and safety of dams	
Risk assessment and safety of earth dams <i>A.Ghirardini & C.Niccolai</i>	197
Embankment dam safety in Sweden <i>U.Norstedt</i>	205
Evaluation of earth dam safety against earthquake <i>B.V.K.Lavania</i>	219
Risk assessment and safety of dams – Static and dynamic behaviors of fill dams <i>T.Tanaka & M.Yasunaka</i>	229
Aspects on safety of dams <i>R.Widmann</i>	239
4. Rehabilitation of dams	
A geotechnical review of the rehabilitation of 19 large dams in Algeria <i>H.W.Hönig & D.J.Paul</i>	249
Dhron curved gravity dam, Germany – First grouting after 73 years of service <i>D.J.Paul</i>	257
Long-term durability of materials for rockfill dams <i>K.Ban</i>	267
Foum el Gherza dam in Algeria – An arch dam under observation in a karstified environment since 1952 <i>D.J.Paul</i>	279
Rehabilitation techniques, from earth dam seepage control to restoration of historical monuments <i>M.Guillaud</i>	287

5. *Materials and miscellaneous topics*

- Durability of concrete sewers in aggressive subsoils and groundwater conditions 299
M.A.Aziz & L.C.C.Koe
- Sulfate attack on concrete: A case history 311
M.I.Sadiq
- Structural effects of creep, shrinkage and expansion in the materials used for the repairing and the strengthening of R.C. structures 317
F.Mola
- The waterproofing of earth-integrated buildings 325
D.W.Baggs
- Survey of Radon in Australian residences 335
S.A.Baggs & C.F.Wong
- Effect of high thermal mass of the earth in underground houses: An overview of earth-covered building in Australia 345
S.A.Baggs
- Influence of ground vibrations and air blast due to heavy blasting on buildings 361
A.G.Paithankar