

**SAFETY COMPLIANCE REPORT/
TERMINAL RECORD UPDATE**

CHP 343 (Rev. 12-17) OPI 062

NEW TERMINAL INFORMATION <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	CA NUMBER 40015	FILE CODE NUMBER 43843	COUNTY CODE 44	BED
TERMINAL TYPE <input type="checkbox"/> Truck <input checked="" type="checkbox"/> Bus <input type="checkbox"/> Mod Limo	CODE B	OTHER PROGRAM(S) 1	LOCATION CODE 720	SUBAREA C44

CARRIER LEGAL NAME UNIVERSITY OF CALIFORNIA	TERMINAL NAME (IF DIFFERENT) UC SANTA CRUZ - TRANSPORTATION	TELEPHONE NUMBER (W/ AREA CODE) (831) 459-2491
---	---	--

TERMINAL STREET ADDRESS (NUMBER, STREET, CITY, ZIP CODE)
1156 HIGH STREET SANTA CRUZ, CA 95064

MAILING ADDRESS (NUMBER, STREET, CITY, ZIP CODE) (IF DIFFERENT FROM ABOVE)
1156 HIGH STREET SANTA CRUZ, CA 95064

LICENSE, FLEET AND TERMINAL INFORMATION

HM LIC. NO.	HWT REG. NO.	IMS LIC. NO.	TRUCKS AND TYPES 5 S	TRAILERS AND TYPES 1 F	PASS VEH. BY TYPE I 29 II	Mod Limo	DRIVERS 39	BIT FLEET SIZE Powered 5 Towed 1
EXP. DATE	EXP. DATE	EXP. DATE	REG. CT.	HW VEH.	HW CONT.	PPB/CSAT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		
TERMINALS IDENTIFIED IN SECTION 34515(b) CVC <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			FILE CODE NUMBERS OF TERMINALS INCLUDED IN INSPECTION AS A RESULT OF SECTION 34515(b) CVC					

EMERGENCY CONTACTS (In Calling Order of Preference)

EMERGENCY CONTACT (NAME) JOSE MEDRANO	DAY TELEPHONE NO. (W/ AREA CODE) (831) 459-2491	NIGHT TELEPHONE NO. (W/ AREA CODE) (831) [REDACTED]
EMERGENCY CONTACT (NAME) TRACY FREEMAN	DAY TELEPHONE NO. (W/ AREA CODE) (831) 459-3228	NIGHT TELEPHONE NO. (W/ AREA CODE) (831) [REDACTED]

ESTIMATED CALIFORNIA MILEAGE FOR THIS TERMINAL FOR LAST YEAR [2023]

A <input type="checkbox"/> UNDER 15,000	B <input type="checkbox"/> 15,001 — 50,000	C <input checked="" type="checkbox"/> 50,001 — 100,000	D <input type="checkbox"/> 100,001 — 500,000	E <input type="checkbox"/> 500,001 — 1,000,000	F <input type="checkbox"/> 1,000,001 — 2,000,000	G <input type="checkbox"/> 2,000,001 — 5,000,000	H <input type="checkbox"/> 5,000,001 — 10,000,000	I <input type="checkbox"/> MORE THAN 10,000,000
--	---	---	---	---	---	---	--	--

OPERATING AUTHORITIES OR PERMITS

PUC <input type="checkbox"/> T	<input type="checkbox"/> TCP <input type="checkbox"/> PSC	MOTOR CARRIER OF PROPERTY PERMIT ACTIVE <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	IMS FITNESS EVALUATION <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
USDOT 2662585	<input type="checkbox"/> MC <input type="checkbox"/> MX	REASON FOR INSPECTION Complaint Investigation	

INSPECTION FINDINGS

REQUIREMENTS	VIOL	INSPECTION RATINGS: S = Satisfactory U = Unsatisfactory C = Conditional UR = Unrated N/A = Not Applicable				
		MAINTENANCE PROGRAM	DRIVER RECORDS	REG. EQUIPMENT	HAZARDOUS MATERIALS	TERMINAL
MAINTENANCE PROGRAM	1	1 S 2 S 3 S 4 U	1 S 2 S 3 S 4 U	1 S 2 S 3 S 4 U	1 N/A 2 N/A 3 N/A 4 N/A	1 S 2 S 3 S 4 U
DRIVER RECORDS	1	No. 9 Time 3.0	No. 18 Time 14.0	No. 9 Time 7.0	TIME 0.0	TOTAL TIME 24.0
DRIVER HOURS		HAZARDOUS MATERIALS <input checked="" type="checkbox"/> No H/M Transported <input type="checkbox"/> No H/M violations noted		CONTAINERS/TANKS No. 0 Time 0.0	VEHICLES PLACED OUT-OF-SERVICE Vehicles 5 Units 0	
BRAKES	5	REMARKS				
LAMPS & SIGNALS	2	36 - Bus Drivers				
CONNECTING DEVICES		See CAPRI report for violations and direction to carrier.				
STEERING & SUSPENSION		Carrier's operations was determined to meet the classification of Imminent Danger to Public Safety as per CVC 34505.7(a)(1) since greater the 50% of the regulated equipment sample was placed Out-Of-Service.				
TIRES & WHEELS	1					
EQUIPMENT REQUIREMENTS	16	A re-inspection is tentatively scheduled for May 6th, 2024.				
CONTAINERS & TANKS						
HAZARDOUS MATERIALS						


INSPECTION TYPE <input type="checkbox"/> I <input type="checkbox"/> R <input checked="" type="checkbox"/>	NON-BIT <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CPSS <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CHP 345 <input checked="" type="checkbox"/>	CHP 100D COL.	INSPECTION DATE(S) 1/3,4,5,8,19/2024	TIME IN 09:00	TIME OUT 11:00
INSPECTED BY (NAME(S)) M. Morales, J. Hopper				ID NUMBER(S) A17298, A19230	SUSPENSE DATE <input checked="" type="checkbox"/> Auto <input type="checkbox"/> None		

MOTOR CARRIER CERTIFICATION

I hereby certify that all violations described hereon and recorded on the attached pages (2 through 28), will be corrected in accordance with applicable provisions of the California Vehicle Code and the California Code of Regulations. I understand that I may request a review of an unsatisfactory rating by contacting the Motor Carrier Safety Unit Supervisor at (805)706-3303 within 5 business days of the rating.

CURRENT TERMINAL RATING UNSATISFACTORY	CARRIER REPRESENTATIVE'S SIGNATURE <i>Theo Diamantopoulos</i>	DATE 01/19/2024
CARRIER REPRESENTATIVE'S PRINTED NAME Theo Diamantopoulos	TITLE Fleet Manager	DRIVER LICENSE NUMBER [REDACTED]
		STATE CA

California Highway Patrol

	US DOT # 2662585	Legal: UNIVERSITY OF CALIFORNIA Operating (DBA): UNIVERSITY OF CALIFORNIA SANTA CRUZ					
MC/MX #:	State #: 40015	Federal Tax ID: 94-1539563 (EIN)					
Review Type: Non-ratable Review - Special Study							
Scope: Terminal	Location of Review/Audit: Company facility in the U. S.		Territory:				
Operation Types							
	Interstate	Intrastate					
Carrier:	N/A	Non-HM	Business: Corporation				
Shipper:	N/A	N/A	Gross Revenue: _____ for year ending: _____				
Cargo Tank:	N/A						
Company Physical Address:							
1156 HIGH ST SANTA CRUZ, CA 95064							
Contact Name:							
Phone numbers: (1) 831- 459-3887		(2)	Fax				
E-Mail Address:							
Company Mailing Address:							
1156 HIGH ST SANTA CRUZ, CA 95064							
Carrier Classification							
Other: Intrastate							
Cargo Classification							
Passengers		Garbage, Refuse, Trash					
Equipment							
	Owned	Term Leased	Trip Leased		Owned	Term Leased	Trip Leased
Truck	5	0	0	Trailer	1	0	0
Minibus, 16+	29	0	0				
Power units used in the U.S.: 34							
Percentage of time used in the U.S.: 100							
Does carrier transport placardable quantities of HM?				No			
Is an HM Permit required?				N/A			
Driver Information							
	Inter	Intra	Average trip leased drivers/month: 0				
< 100 Miles:	36		Total Drivers: 36				
>= 100 Miles:			CDL Drivers: 36				





UNIVERSITY OF CALIFORNIA SANTA CRUZ (UNIVERSITY OF dba) - Terminal

U.S. DOT #: 2662585

State #: 40015

Review Date:

01/19/2024

Part A

QUESTIONS regarding this report may be directed to the Coastal Division
Motor Carrier Safety Unit at:

4115 Broad Street, Ste B-10
San Luis Obispo, Ca 93401
805-706-3303

This TERMINAL REVIEW deals only with safety compliance at this terminal.

Person(s) Interviewed

Name: Tracy Freeman

Title: Transit Manager

Name: Theo Diamantopoulos

Title: Fleet Manager





UNIVERSITY OF CALIFORNIA SANTA CRUZ (UNIVERSITY OF dba) - Terminal
 U.S. DOT #: 2662585 State #: 40015

Review Date:
 01/19/2024

Part B Violations

1 STATE	Primary: 14606(a)CVC CFR Equivalent: 391.11(a)	Discovered 1	Checked 18	Drivers/Vehicles In Violation 1	Checked 18
------------	---	-----------------	---------------	---------------------------------------	---------------

Description

Carrier employed, hired, knowingly permitted or authorized a driver to drive a motor vehicle owned by him/her or under his/her control upon the highways without a valid license for the appropriate class of vehicle to be driven.

Example

Carrier allowed driver, [REDACTED], to drive bus # 7926 (CA 1345631, GVWR 36000 lbs. 34 pax) without a valid CDL on 11/27/2023 per route sheet, DVIR and timecard. [REDACTED] has an expired medical on file with the DMV, the expiration date is 06/06/2022 per CDLIS. CDLIS was ran on 01/05/2024.





UNIVERSITY OF CALIFORNIA SANTA CRUZ (UNIVERSITY OF dba) - Terminal

U.S. DOT #: 2662585

State #: 40015

Review Date:

01/19/2024

Part B Violations

2 STATE	Primary: 13CCR 1232(a)(1) CFR Equivalent: 396.3(b)(2)	Discovered 1	Checked 9	Drivers/Vehicles In Violation 9	Checked 9
------------	--	-----------------	--------------	---------------------------------------	--------------

Description

The motor carrier fails to inspect emergency exits at least once every 90 days. Carrier fails to inspect the emergency exits every 90 days. The following vehicles are in violation:

Bus 7934

Inspection done on 03/30/2022, next inspection due on 06/28/2022, inspection was performed on 03/31/2023, past due 276 days.

Inspection done on 03/31/2023, next inspection due on 06/29/2023, inspection was performed on 08/25/2023, past due 57 days.

Bus 7928

Inspection done on 06/29/2022, next inspection due on 09/27/2022, inspection was performed on 03/27/2023, past due 181 days.

Inspection done on 03/27/2023, next inspection due on 06/25/2023, inspection was performed on 12/11/2023, past due 169 days.

Bus 7926

Inspection done on 10/24/2022, next inspection due on 01/22/2023, inspection was performed on 06/22/2023, past due 90 days.

Inspection done on 06/22/2023, next inspection on due 09/20/2023, inspection was not performed, past due 107 days.

Bus 7929

Inspection done on 04/04/2022, next inspection due on 07/03/2022, inspection was performed on 02/13/2023, past due 225 days.

Inspection done on 02/13/2023, next inspection due on 05/14/2023, inspection was performed on 08/15/2023, past due 93 days.

Inspection done on 08/15/2023, next inspection due on 11/13/2023, inspection was not performed, past due 53 days.

Bus 7938

Inspection done on 07/20/2022, next inspection due on 10/18/2022, inspection was performed on 03/06/2023, past due 139 days.

Inspection done on 03/06/2023, next inspection due on 06/04/2023, inspection was performed on 08/11/2023, past due 68 days.

Inspection done on 08/11/2023, next inspection due on 11/09/2023, inspection was not performed, past due 57 days.

Bus 7921

Inspection done on 04/04/2022, next inspection due on 07/03/2022, inspection was performed on 02/13/2023, past due 225 days.

Inspection done on 02/13/2023, next inspection due on 05/14/2023, inspection was performed on 08/15/2023, past due 93 days.

Inspection done on 08/15/2023, next inspection due on 11/13/2023, inspection was not performed, past due 53 days.

Bus 7936

Inspection done on 07/07/2022, next inspection due on 10/05/2022, inspection was performed on 06/08/2023, past due 246 days.

Inspection done on 06/08/2023, next inspection due on 09/06/2023, inspection was not performed, past due 121 days.

Bus 7920

Inspection done on 10/12/2022, next inspection due on 01/10/2023, inspection was performed on 05/18/2023, past due 128 days.

Inspection done on 05/18/2023, next inspection due on 08/16/2023, inspection was not performed, past due 142 days.

Bus 7939





Part B Violations

Inspection done on 02/10/2022, next inspection due on 05/11/2022, inspection was performed on 07/11/2023, past due 426 days.

Inspection done on 07/11/2023, next inspection due on 10/09/2023, inspection was not performed, past due 88 days.

Carrier fails to systematically inspect the following vehicles at their set intervals of 6 months or 6,000 miles:

Bus 7934

Inspection done on 03/30/2022 @ 657,628, next inspection due on 09/30/2022 or 663,628 miles, inspection was performed on 03/31/2023 @ 664,556, past due 182 days and 928 miles.

Bus 7928

Inspection done on 06/29/2022 @ 550183 miles, next inspection due on 12/29/2022 or 556183 miles, inspection was performed on 03/27/2023 @ 556447 miles, past due 88 days and 264 miles.

Inspection done on 03/27/2023 @ 556,447 miles, next inspection due on 09/27/2023 or 562,447 miles, inspection was performed on 12/11/2023 @ 562,594 miles, past due 75 days and 147 miles.

Bus 7926

Inspection done on 10/24/2022 @ 495,814 miles, next inspection due on 04/24/2023 or 501,814 miles, inspection was performed on 06/22/2023 @ 502,111 miles, past due 59 days and 297 miles.

Inspection done on 06/22/2023 @ 502111, next inspection due on 12/22/2023 or 508,111 miles, inspection was not performed, past due 14 days.

Bus 7929

Inspection done on 04/04/2022 @ 76186 miles, next inspection due on 10/04/2022 or 82,186 miles, inspection was performed on 02/13/2023 @ 82,471 miles, past due 132 days and 285 miles.

Inspection done on 02/13/2023 @ 82471, next inspection due on 08/13/2023 or 88,471 miles, inspection was performed on 08/15/2023 @ 88,873 miles, past due 2 days and 402 miles.

Bus 7938

Inspection done on 07/20/2022 @ 158,671 miles, next inspection due on 01/20/2023 or 164,671 miles, inspection was performed on 03/06/2023 @ 167,621 miles, past due 45 days and 2,950 miles.

Inspection done on 03/06/2023 @ 167,621 miles, next inspection due on 09/06/2023 or 173,621 miles, inspection was performed on 08/11/2023 @ 174,371, past due 750 miles.

Bus 7921

Inspection done on 04/04/2022 @ 76186 miles, next inspection due on 10/04/2022 or 82,186 miles, inspection was performed on 02/13/2023 @ 82,471 miles, past due 132 days and 285 miles.

Inspection done on 02/13/2023 @ 82,471 miles, next inspection due on 08/13/2023 or 88,471 miles, inspection was performed on 08/15/2023 @ 88,873, past due 2 days and 402 miles.

Bus 7936

Inspection done on 07/07/2022 @ 104,715 miles, next inspection due on 01/07/2023 or 110,715 miles, inspection was performed on 06/08/2023 @ 111,564 miles, past due 152 days and 849 miles.

Inspection done on 06/08/2023, next inspection due on 12/08/2023, inspection was not performed, past due 28 days.

Bus 7920

Inspection done on 10/12/2022, next inspection due on 04/12/2023, inspection was performed on 05/08/2023, past due 26 days.

Inspection done on 05/08/2023, next inspection due on 11/08/2023, inspection was not performed, past due 58 days.

Bus 7939

Inspection done on 02/10/2022, next inspection due on 08/10/2022, inspection was performed on 07/11/2023, past due 335 days.





UNIVERSITY OF CALIFORNIA SANTA CRUZ (UNIVERSITY OF dba) - Terminal
U.S. DOT #: 2662585 State #: 40015

Review Date:
01/19/2024

Part B Violations

Safety Fitness Rating Information:

Total Miles Operated 90,000
Recordable Accidents 0

OOS Vehicle (CR): 5
Number of Vehicle Inspected (CR): 9
OOS Vehicle (MCMIS): 0
Number of Vehicles Inspected (MCMIS): 0

Your proposed safety rating is :

This Review is not Rated.





Part B Requirements and/or Recommendations

1. As a result of this inspection, the terminal has been assigned an UNSATISFACTORY safety compliance rating and the motor carrier is deemed an imminent danger, as defined in Title 13, California Code of Regulations, Section 1233(f), for the following:
2. More than 50 percent of vehicles in the inspection sample placed out-of-service. 5 of 9 = 55.56%
3. Utilizing an unqualified driver.
4. As a result of violation(s) noted during this inspection the motor carrier is directed to comply with the following:
5. Do not allow drivers to operate commercial motor vehicles unless they are medically qualified.
6. Ensure all drivers with a Commercial Driver License to have a current and valid medical certificate on file with the DMV. Failure to have medical on file with DMV results in the driver's Commercial Driver License to revert to a non-commercial class C license.
7. Ensure all emergency exits on all buses are inspected at least once every 90 days.
8. Periodically inspect all vehicles subject to your control, at least Annually or more often if necessary to ensure safe and proper operation. This inspection shall include, but not be limited to, all of the following: brake adjustment, brake system components and leaks, steering and suspension systems, tires and wheels and vehicle connecting devices. Records of periodic inspections shall be maintained on file for two years.





UNIVERSITY OF CALIFORNIA SANTA CRUZ (UNIVERSITY OF dba) - Terminal
 U.S. DOT #: 2662585 State #: 40015

Review Date:
01/19/2024

Part C

Reason for Review: Other Complaint Investigat
Planned Action: Compliance Monitoring

Parts Reviewed Certification:

325 382 383 387 390 391 392 393 395 396 397 398 399 171 172 173 177 178 180

Prior Reviews **Prior Prosecutions** **Reason not Rated:** Special Study **Study Code:** CA
 9/8/2022
 9/8/2022
 9/7/2021

Unsat/Unfit Information

Is the motor carrier of passengers subject to the safety fitness procedures contained in 49 CFR part 385 subpart A, AND does it transport passengers in a commercial motor vehicle? No

Does carrier transport placardable quantities of hazardous materials?
Unsat/Unfit rule: Not Applicable

Corporate Contact: Tracy Freeman **Special Study Information:**
Corporate Contact Title: Transit Manager

Remarks:

TERMINAL NAME: UC SANTA CRUZ - TRANSPORTATION CA # - 40015
 Terminal Address: 1156 HIGH STREET, SANTA CRUZ, CA 95064 FCN - 43843

RATING INFORMATION:

In accordance with 13 CCR 1233, this Terminal has been rated Unsatisfactory at this time.

As a result of the inspection findings noted above, and documented in Part B of this report, this terminal has been rated unsatisfactory due to:

More than 50% of the inspected vehicles being placed out of service.

Utilizing unqualified drivers.

Rating Information: In accordance with 13 CCR 1233, this terminal has been rated Unsatisfactory at this time. 55.56% of the carrier's regulated equipment inspection sample, 5 of 9 were placed Out-Of-Service during the terminal inspection. Regulated equipment condition indicates the carrier's inspection and maintenance program is not effective. The vehicle violations should have been detected during an effective maintenance program and driver's daily vehicle inspections. Carriers' maintenance program was assigned an Unsatisfactory rating due to the condition of the regulated equipment. Carrier's operation was determined to meet the classification of Imminent Danger to Public Safety as per CVC 34505.7(a)(1) since greater than 50% of the regulated equipment sample was placed Out-Of-Service.

OUT-OF-SERVICE (OOS) VEHICLES:

13 CCR 1230(a) - The following vehicles were placed OOS during this terminal inspection. The below listed vehicles shall not be operated on the highway until all OOS defects are corrected.

- 920 - Brakes out of adjustment & air brake hose worn into reinforcement ply.
- 926 - Brakes out of adjustment.
- 928 - Brakes out of adjustment & emergency exit inoperable.
- 929 - Emergency exit inoperable.
- 938 - Brakes out of adjustment & emergency exit does not close as designed.

A re-inspection will be conducted within 120 days of the date of the inspection. The California Highway Patrol will attempt to contact your company within the 100-day period to schedule the re-inspection. It is the motor carrier's responsibility,





UNIVERSITY OF CALIFORNIA SANTA CRUZ (UNIVERSITY OF dba) - Terminal
U.S. DOT #: 2662585 State #: 40015

Review Date:
01/19/2024

Part C

however, to ensure that all required records are made available for the re-inspection, and that the re-inspection is conducted within the allotted time frame.

A re-inspection is tentatively scheduled for May 6th, 2024.

Upload Authorized:	Yes	No
Authorized by:		Date:
Uploaded:	Yes	No
Verified by:		Failure Code:
		Date:





California Highway Patrol
 4115 Broad Street, #B-10
 San Luis Obispo, CA 93401
 Phone: (805) 549-3261
 Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000078
Inspection Date: 01/03/2024
Start: 8:00 AM PT **End:** 8:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
 1156 HIGH ST
 SANTA CRUZ, CA, 95064

USDOT: 2662585 **Phone#:** (831)459-3887
MC/MX#: **Fax#:** (831)459-5259

State#: 40015

Location: UC SANTA CRUZ

Highway:

County: SANTA CRUZ

Email: VSCHLEGE@UCSC.EDU

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

Milepost: **Shipper:** N/A

Origin: SANTA CRUZ,CA

Bill of Lading: N/A

Destination: SANTA CRUZ,CA

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1345635	934	15GCB0919P1084934	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/4	1 1/2
Left	1 1/4	1 1/2
Chamber	C-24	C-36

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:	Alcohol/Controlled Substance Check	X Traffic Enforcement	Post Crash Inspection
	Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
	Size and Weight Enforcement	Drug Interdiction Search	
	eScreen Inspection		

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.

Report Prepared By:

C. Hicks

Unit #:

701

ID/Badge #:

18996

Copy Received By:

X

X



02662585 CA CAUENO000078



California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000079
Inspection Date: 01/03/2024
Start: 8:30 AM PT End: 9:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA
DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
1156 HIGH ST
SANTA CRUZ, CA, 95064
USDOT: 2662585 Phone#: (831)459-3887
MC/MX#: Fax#: (831)459-5259
State#: 40015
Location: UC SANTA CRUZ
Highway:
County: SANTA CRUZ
Email: VSCHLEGE@UCSC.EDU

Driver:
License#: **State:**
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:
Milepost: Shipper: N/A
Origin: SANTA CRUZ,CA
Destination: SANTA CRUZ,CA
Bill of Lading: N/A
Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	11345633	928	15GCB0915P1084946	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	1 1/2
Left	2 1/2	1 1/2
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
1239 T-13 CCR/326	S	1	Y		U N	Passenger-carrying vehicle (Bus), marked emergency exit is inoperative or obstructed OOS violation--393.62A--Specify:: 1 OF 10 EMERGENCY EXIT INOP
24252(a) CVC/005	S	1	N		N N	License plate lamp inoperative--393.9: REAR PLATE LIGHT INOP
1239 T-13 CCR/055	S	1	Y		U N	Brakes out of Service: The number of defective brakes is equal to or greater than 20% of the service brakes on the vehicle(s) OOS violation--396.3A1BOS--Specify:: 1 OF 4 BRAKES OUT OF ADJUSTMENT- OVER 20% -- LF AX1 OUT OF ADJUSTMENT

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:	Alcohol/Controlled Substance Check Conducted by Local Jurisdiction	Size and Weight Enforcement	eScreen Inspection	Traffic Enforcement	PASA Conducted Inspection	Drug Interdiction Search	Post Crash Inspection	PBBT Inspection
				X				

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: removed 34500.7(a) CVC/064 and viol of 24002(a) VC, per A13937 - 01/08/2024 - 20912

NOTES: AX1 RIGHT SIDE TORSSION ARM MISSING BOLT

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000079
Inspection Date: 01/03/2024
Start: 8:30 AM PT End: 9:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.

<u>Report Prepared By:</u>	<u>Unit #:</u>	<u>ID/Badge #:</u>	<u>Copy Received By:</u>
C. Hicks	701	18996	

X

X





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000080
Inspection Date: 01/03/2024
Start: 9:00 AM PT End: 9:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
1156 HIGH ST
SANTA CRUZ, CA, 95064

USDOT: 2662585

Phone#: (831)459-3887

MC/MX#:

Fax#: (831)459-5259

State#: 40015

Location: UC SANTA CRUZ

Highway:

County: SANTA CRUZ

Email: VSCHLEGE@UCSC.EDU

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

Milepost:

Shipper: N/A

Origin: N/A

Bill of Lading: N/A

Destination: N/A

Cargo: N/A

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1345631	926	15GCB0912P1084953	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 3/4	1 1/2
Left	2	2
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1239 T-13 CCR/055	S	1	Y		U	N	Brakes out of Service: The number of defective brakes is equal to or greater than 20% of the service brakes on the vehicle(s) OOS violation--396.3A1BOS-- Specify:: 1 OF 4 BRAKES OUT OF ADJUSTMENT- OVER 20% -- AX1 L/S OUT OF ADJUSTMENT
27900(a) CVC	S	1	N		N	N	Carrier name or trademark is not displayed on both sides of vehicle--390.21TA-- Specify:: ONLY DISPLAYED ON THE BACK- NOT ON SIDES
1269(b)(3) T-13 CCR	S	1	N		N	N	Emergency exit window operating instructions required--392.2: FRONT EXIT NO OPERATING INSTRUCTIONS

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:	Alcohol/Controlled Substance Check	Traffic Enforcement	Post Crash Inspection
	Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
	Size and Weight Enforcement	Drug Interdiction Search	
	eScreen Inspection		

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: removed 34500.7(a) CVC/084 and moved notes to 1239 T-13 CCR/055. Changes 1239 T-13 CCR/325 to 1269b3 T-13. Both changes per A13937 - 01/08/2024 - 20912

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainsttrafficking.org/> to learn more.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000080
Inspection Date: 01/03/2024
Start: 9:00 AM PT End: 9:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Report Prepared By: Unit #: ID/Badge #: Copy Received By:
C. Hicks 701 18996

X

X





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000081
Inspection Date: 01/03/2024
Start: 9:30 AM PT End: 10:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
 1156 HIGH ST
 SANTA CRUZ, CA, 95064

USDOT: 2662585 **Phone#: (831)459-3887**
MC/MX#: **Fax#: (831)459-5259**

State#: 40015

Location: UC SANTA CRUZ

Highway:

County: SANTA CRUZ

Email: VSCHLEGE@UCSC.EDU

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

Milepost: **Shipper: N/A**

Origin: SANTA CRUZ,CA

Bill of Lading: N/A

Destination: SANTA CRUZ,CA

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1345634	929	15GCB0918P1084813	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	1 3/4
Left	1 1/2	1 3/4
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1239 T-13 CCR/325	S	1	Y		U	N	Passenger-carrying vehicle (Bus), required emergency exit is missing, inoperative, not properly marked or obstructed OOS violation--393.62A--Specify: L/S WINDOW #2 EMERGENCY EXIT INOP- THIS WITH THE UNMARKED FRONT EXIT ON THE SAME SIDE (RIGHT) IS 2 OF 5 EXITS= 40% MAKES IT OOS
1269(b)(3) T-13 CCR	S	1	N		N	N	Emergency exit window operating instructions required--392.2: FRONT LEFT AND RIGHT EMERGENCY EXITS NOT PROPERLY LABELED

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:	Alcohol/Controlled Substance Check	Traffic Enforcement	Post Crash Inspection
	Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
	Size and Weight Enforcement	Drug Interdiction Search	
	eScreen Inspection		

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: update 1239 T-13 CCR/325 to 1269b3 T-13 and removed 24002(a) VC - per A13937 - 01/08/2024 - 20912

NOTE: TELESCOPIC STEERING COLUMN DOES NOT ADJUST AS DESIGNED (UP/DOWN)

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000081
Inspection Date: 01/03/2024
Start: 9:30 AM PT End: 10:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Report Prepared By: Unit #: ID/Badge #: Copy Received By:
C. Hicks 701 18996

X

X





California Highway Patrol
 601 North 7th Street
 Sacramento, CA 95811
 Phone: (916) 843-3400
 Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000082
Inspection Date: 01/03/2024
Start: 10:30 AM PT **End:** 11:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
 1156 HIGH ST
 SANTA CRUZ, CA, 95064

USDOT: 2662585 **Phone#:** (831)459-3887

MC/MX#: **Fax#:** (831)459-5259

State#: 40015

Location: UC SANTA CRUZ

Highway:

County: SANTA CRUZ

Email: VSCHLEGE@UCSC.EDU

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

Milepost: **Shipper:** N/A

Origin: SANTA CRUZ,CA

Bill of Lading: N/A

Destination: SANTA CRUZ,CA

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1436086	938	15GCB0910P1084921	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 3/4	1 1/2
Left	1 1/2	3 1/4
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1239 T-13 CCR/325	S	1	Y		U	N	Passenger-carrying vehicle (Bus), required emergency exit is missing, inoperative, not properly marked or obstructed OOS violation--393.62A--Specify:: R/SIDE 3RD WINDOW EMER. EXIT DOES NOT CLOSE AS DESIGNED
1269(b)(3) T-13 CCR	S	1	N		N	N	Emergency exit window operating instructions required--392.2: L/SIDE 1ST WINDOW HAS NO INSTRUCTIONS
1239 T-13 CCR/055	S	1	Y		U	N	Brakes out of Service: The number of defective brakes is equal to or greater than 20% of the service brakes on the vehicle(s) OOS violation--396.3A1BOS-- Specify:: AX2 L OUT OF ADJUSTMENT- OVER 20%- OOS
26707 CVC	S	1	N		N	N	Windshield wipers are inoperative or defective--393.78--Specify:: RIGHT SIDE WIPER INOP

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:	Alcohol/Controlled Substance Check	Traffic Enforcement	Post Crash Inspection
	Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
	Size and Weight Enforcement	Drug Interdiction Search	
	eScreen Inspection		

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: 1239 T-13/325 updated OOS from "N" to "Y" (#1 viol), 1239 T-13/325 updated to 1269b3 T-13 (viol #2), and removed 1239 T-13/325 (viol #3 - moved to notes) - per A13937 - 01/08/2024 - 20912

NOTE: FORWARD ROOF HATCH BROKEN LATCH- DOES NOT SECURE

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000082
Inspection Date: 01/03/2024
Start: 10:30 AM PT End: 11:00 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.

<u>Report Prepared By:</u>	<u>Unit #:</u>	<u>ID/Badge #:</u>	<u>Copy Received By:</u>
C. Hicks	701	18996	

X

X





California Highway Patrol
 601 North 7th Street
 Sacramento, CA 95811
 Phone: (916) 843-3400
 Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000083
Inspection Date: 01/03/2024
Start: 11:00 AM PT **End:** 11:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
 1156 HIGH ST
 SANTA CRUZ, CA, 95064

USDOT: 2662585 **Phone#:** (831)459-3887
MC/MX#: **Fax#:** (831)459-5259

State#: 40015

Location: UC SANTA CRUZ

Highway:

County: SANTA CRUZ

Email: VSCHLEGE@UCSC.EDU

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

Milepost: **Shipper:** N/A

Origin: SANTA CRUZ,CA

Bill of Lading: N/A

Destination: SANTA CRUZ,CA

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1353255	936	15GCB0911P1084927	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 1/2	1 3/4
Left	1 1/2	1 3/4
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
1269(b)(3) T-13 CCR	S	1	N		N	N	Emergency exit window operating instructions required--392.2: FRONT LEFT AND RIGHT EMERGENCY EXIT WINDOWS NO LABEL
34507.5(b) CVC/001	S	1	N		N	N	Vehicle does not have a carrier number displayed--390.21TB: NO CA# ON EITHER SIDE

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:

Alcohol/Controlled Substance Check
 Conducted by Local Jurisdiction
 Size and Weight Enforcement
 eScreen Inspection

X Traffic Enforcement
 PASA Conducted Inspection
 Drug Interdiction Search

Post Crash Inspection
 PBBT Inspection

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: viol #1 1239 T-13/325 updated to 1269b3 T-13 and 1239 T-13 (viol #2) removed and added in "NOTES", per A13937 - 01/08/2024 - 20912

NOTES: REAR ROOF HATCH CRACKED

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000083
Inspection Date: 01/03/2024
Start: 11:00 AM PT End: 11:30 AM PT
Inspection Level: V - Terminal
HM Inspection Type: None

<u>Report Prepared By:</u>	<u>Unit #:</u>	<u>ID/Badge #:</u>	<u>Copy Received By:</u>
C. Hicks	701	18996	

X

X





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000084
Inspection Date: 01/03/2024
Start: 11:30 AM PT End: 12:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
 1156 HIGH ST
 SANTA CRUZ, CA, 95064

USDOT: 2662585

Phone#: (831)459-3887

MC/MX#:

Fax#: (831)459-5259

State#: 40015

Location: UC SANTA CRUZ

Highway:

County: SANTA CRUZ

Email: VSCHLEGE@UCSC.EDU

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

Milepost: Shipper: N/A

Origin: SANTA CRUZ,CA

Bill of Lading: N/A

Destination: SANTA CRUZ,CA

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1345626	920	15GCB0914P1084937	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	2	1 3/4
Left	2	1 3/4
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
34507.5(b) CVC/002	S	1	N		N	Vehicle does not have a carrier number displayed on both sides of the vehicle--390.21TB--Specify:: NO CA # LEFT SIDE
27315(f) CVC/001	S	1	N		N	Owner of a motor vehicle fail to maintain seatbelts in good working order--393.93B-SBA--Specify:: DRIVER SEATBELT DOES NOT EXTEND FAR ENOUGH TO LATCH
1269(b)(3) T-13 CCR	S	1	N		N	Emergency exit window operating instructions required--392.2: 1ST WINDOW RIGHT SIDE- NO INSTRUCTIONS
1239 T-13 CCR/085	S	1	Y		U	Air brake hose or tubing has damage through the reinforcement ply OOS violation--393.45--Specify:: AX2 L/SIDE EMERGENCY/SERVICE AIR LINES WORN THROUGH REINFORCEMENT PLY
1239 T-13 CCR/055	S	1	Y		U	Brakes out of Service: The number of defective brakes is equal to or greater than 20% of the service brakes on the vehicle(s) OOS violation--396.3A1BOS--Specify:: AX1 BOTH SIDES OUT OF ADJUSTMENT- OVER 20%- OOS

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:	Alcohol/Controlled Substance Check	X	Traffic Enforcement	Post Crash Inspection
	Conducted by Local Jurisdiction		PASA Conducted Inspection	PBBT Inspection
	Size and Weight Enforcement		Drug Interdiction Search	
	eScreen Inspection			

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: 1239 T-13/325 (viol #3) updated to 1269b3 T-13, 1239 T-13/325 (viol #4) removed and added to "NOTES," and note for viol #5 1239/085 update with more details, per A13937 - 01/08/2024 - 29012

NOTES: FRONT HATCH CRACKED AT ATTACHMENT POINT

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000085
Inspection Date: 01/03/2024
Start: 12:30 PM PT End: 1:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
 1156 HIGH ST
 SANTA CRUZ, CA, 95064

Driver:
License#: **State:**
Date of Birth:

USDOT: 2662585 **Phone#: (831)459-3887**

CoDriver:
License#: **State:**
Date of Birth:

MC/MX#: **Fax#: (831)459-5259**

State#: 40015

Location: UC SANTA CRUZ

Milepost: **Shipper: N/A**

Highway:

Origin: SANTA CRUZ,CA

Bill of Lading: N/A

County: SANTA CRUZ

Destination: SANTA CRUZ,CA

Cargo: EMPTY

Email: VSCHLEGE@UCSC.EDU

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1436085	939	15GCB0911P1084815	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1 3/4	2 1/4
Left	1 1/2	2 1/4
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	OOS	Citation #	VerifyCrash	Violations Discovered
1269(b)(3) T-13 CCR	S	1	N		N N	Emergency exit window operating instructions required--392.2: FRONT LEFT EXIT- NO INSTRUCTIONS
24252(a) CVC/005	S	1	N		N N	License plate lamp inoperative--393.9: LICENSE PLATE LIGHT INOP
27465(b)(1) CVC	S	1	N		N N	Tire tread depth is less than 1/32 inch--392.2--Specify:: AX2 LEFT INNER TIRE- INSIDE TREAD <1/32

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:	Alcohol/Controlled Substance Check	X Traffic Enforcement	Post Crash Inspection
	Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
	Size and Weight Enforcement	Drug Interdiction Search	
	eScreen Inspection		

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: VIOL #1 1239 T-13/325 UPDATED TO 1269b3 T-13, AND VIOL #3 1239 T-13/293 UPDATED TO 27465 VC - PER A13937 - 01/08/2024 - 20912

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000085
Inspection Date: 01/03/2024
Start: 12:30 PM PT End: 1:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Report Prepared By:
C. Hicks

Unit #:
701

ID/Badge #:
18996

Copy Received By:

X

X





California Highway Patrol
 601 North 7th Street
 Sacramento, CA 95811
 Phone: (916) 843-3400
 Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000086
Inspection Date: 01/03/2024
Start: 1:30 PM PT **End:** 2:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

Carrier: UNIVERSITY OF CALIFORNIA

DBA: UNIVERSITY OF CALIFORNIA SANTA CRUZ
 1156 HIGH ST
 SANTA CRUZ, CA, 95064

USDOT: 2662585 **Phone#:** (831)459-3887

MC/MX#: **Fax#:** (831)459-5259

State#: 40015

Location: UC SANTA CRUZ

Highway:

County: SANTA CRUZ

Email: VSCHLEGE@UCSC.EDU

Driver:

License#:

State:

Date of Birth:

CoDriver:

License#:

State:

Date of Birth:

Milepost:

Shipper: N/A

Origin:

Bill of Lading: N/A

Destination:

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	GILG	1993	CA	1345627	921	15GCB0916P1084938	39600		

BRAKE ADJUSTMENTS

Axle #	1	2
Right	1	1 3/4
Left	1	1 3/4
Chamber	C-24	C-36

VIOLATIONS

Section	Type	Unit	QOS	Citation #	VerifyCrash	Violations Discovered
1269(b)(3) T-13	S	1	N		N N	Emergency exit window operating instructions required--392.2: 1ST WINDOWS L&R
CCR						SIDES MISSING EXIT INSTRUCTIONS
27900(a) CVC	S	1	N		N N	Carrier name or trademark is not displayed on both sides of vehicle--390.21TA-- Specify: TRADEMARK IS ON REAR ONLY

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:

Alcohol/Controlled Substance Check
 Conducted by Local Jurisdiction
 Size and Weight Enforcement
 eScreen Inspection

X Traffic Enforcement
 PASA Conducted Inspection
 Drug Interdiction Search

Post Crash Inspection
 PBBS Inspection

State Information:

Beat/Sub Area: C44; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Veh #1 Type: 11

Co-Inspector(s):

Farias-Morales (A17298)

Notes: updated 1239 T-13/325 (viol #1) to 1269b3 T-13 and removed 1239 T-13/325 (viol #2) and moved to "NOTES," per A13937 - 01/08/2024 - 20912

NOTES: REAR ROOF HATCH LATCH CRACKED

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.

TRUCKERS AGAINST TRAFFICKING

TRUCKERS AGAINST TRAFFICKING - If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.





California Highway Patrol
601 North 7th Street
Sacramento, CA 95811
Phone: (916) 843-3400
Internationally Accredited Agency CHP407F/343A

Report Number: CAUENO000086
Inspection Date: 01/03/2024
Start: 1:30 PM PT End: 2:00 PM PT
Inspection Level: V - Terminal
HM Inspection Type: None

<u>Report Prepared By:</u>	<u>Unit #:</u>	<u>ID/Badge #:</u>	<u>Copy Received By:</u>
C. Hicks	701	18996	

X

X



NOTICE TO CARRIER

CHP 345 (REV 1-19) OPI 062

INSPECTION DATE

1/3,4,5,8, 19/2024

TERMINAL NAME

UC SANTA CRUZ - TRANSPORTATION

ADDRESS

1156 HIGH STREET, SANTA CRUZ, CA 95064

CARRIER NAME (IF DIFFERENT)

UNIVERSITY OF CALIFORNIA

PRINCIPAL (OWNERSHIP)

LARRY E PAGELER

The motor carrier terminal named above was inspected this date and has been rated UNSATISFACTORY. This is the 1st unsatisfactory rating. As indicated on the accompanying Carrier Inspection/Safety Compliance Report, the principal areas of noncompliance are: (Carrier is to initial spaces beside each box checked.)

- TJD Maintenance Program/Records Pull-Notice Program Hazardous Materials
- TJD Driver Records/Hours of Service TJD Vehicles/Tanks/Containers Drug & Alcohol Test Program

You are advised that:

- Failure to correct the noted deficiencies and to upgrade compliance to satisfactory before the next inspection (see below) may result in action number(s) _____ below by this Department.
- TJD As a result of the inspection findings indicated above, this Department will initiate action number(s) 4,5,6 below without further notice. You may, within 5 business days of this notice, request a review of the inspection findings and the action(s) to be taken. To request a prompt and impartial review by the Division Special Services Commander, contact Coastal Division at 805-706-3303.
- 1. A recommendation to the Department of Motor Vehicles (DMV) to suspend or revoke your motor carrier of property permit _____ or private carrier of passengers certificate _____; Public Utilities Commission (PUC) to deny, suspend, or revoke your operating authority _____; Department of Consumer Affairs (DCA) to suspend, or revoke your operating authority _____. Carrier is placed on notice that the DMV/PUC/DCA will deny or suspend its permit, operating authority, or private carrier of passengers certificate on receipt of a written recommendation from the CHP, without further notice to the carrier. The DMV/PUC/DCA may thereafter revoke the carrier's permit, operating authority, or private carrier of passengers certificate.
- 2. A recommendation to the Department of Toxic Substances Control for administrative action, to include possible suspension, denial, revocation or assessment of significant monetary penalties regarding Hazardous Waste Transporter Registration, Number _____.
- 3. Suspension or revocation of your Hazardous Materials Transportation License, Number _____; Inspection and Maintenance Station License, Number _____; or School Bus Contractor License, Number _____.
- TJD 4. A complaint being filed with the District Attorney's office for prosecution. (A criminal or civil action may follow.)
- TJD 5. A recommendation to the Federal Motor Carrier Safety Administration for administrative action against your United States Department of Transportation registration.
- TJD 6. Other: Actions deemed necessary by the Department.
- A reinspection is required in 120 days(s) tentatively scheduled in 108 day(s).
- After a recommendation has been forwarded to the DMV/PUC/DCA, no reinspection will be conducted for the purpose of operating authority or permit reinstatement until requested by the DMV/PUC/DCA.

If you desire further information concerning this notice, you may telephone the Coastal Division Motor Carrier Safety Unit at 805-706-3303

I acknowledge receipt and understanding of the above notice.

SIGNATURE <u>Theo Diamantopoulos VCSC</u>		TITLE Fleet Manager	
NAME (PRINTED) Theo Diamantopoulos	DRIVER LICENSE NUMBER [REDACTED]	STATE CA	DATE 01/19/2024
ISSUED BY M. MORALES, J. HOPPER		I.D. NUMBER	