

Supplementary Info:




Fig. S1. (a) A representative micrograph of a bottom-facing trench and the orientation of line-scans measured using a stylus profilometer. (b) A representative line-scan of median roughness ($R_a = 2.54 \mu\text{m}$).